

5420 Distributor Drive, Richmond, Virginia 23225 Class A contractor license number 2701 029209A

Dust Removal Recommendations

	Our certified duct cleaning technicians use the Rotobrush duct cleaning machine which is the best duct cleaning machine available. This machine cleans ducts using a high powered HEPA filtered vacuum with a high speed rotating scrub brush lead by a video camera system. This will remove debris that is lodged in the ducts system. \$
Batera Ceiling Mount Wall Mount	One of the most prominent causes for high household dust is duct leakage. Sealing the ducts can prevent your HVAC system from dragging air in from the crawl space or attic. This will also decrease HVAC operation costs. \$
Polen Mold/Spore Fungi Smoke Celing Mount Dust Particles Filter Pet Dander Filter Wall	Honeywell FC40 or F100 will remove large amounts of particulate from the air and can be effective from 6 months to a year.
	Excessive dryer lint can be a contributor to household dust. Dryer vent cleanings can also increase dryer efficiency.



5420 Distributor Drive, Richmond, Virginia 23225 Class A contractor license number 2701 029209A

Suggestions to remove source contributors of Allergies and Asthmas

	Our certified duct cleaning technicians use the Rotobrush duct cleaning machine which is the best duct cleaning machine available. This machine cleans ducts using a high powered HEPA filtered vacuum with a high speed rotating scrub brush lead by a video camera system. This will remove debris that is lodged in the ducts system. \$
	Honeywell's TrueCLEAN air cleaner will remove particulate including microscopic organisms from the air. Cells are easily removed and vacuumed off every 6 months. \$
	Honeywell's UV light is designed to eliminate living organisms such as microbial activity at the source. The evaporator coil is consistently damp in a dark place within the air stream of the system. This light shines UV rays on this area to eliminate any microbial infestations. \$
Bacteria Ceiling Mount Wall Mount Polen Mold/Spore Fungi Smole Dust Particles Filter Grille Filter Filter Grille Wall W W W W W Wall W W Wall W W Wall W W W Wall W Wall W W W W W	High efficiency media air cleaners such as the Honeywell FC40 or F100 will remove large amounts of particulate including pollen and spores from the air and can be effective from 6 months to a year.