

Name	Sales Desc	Price
2-10 20085	Emergency Drain Pan	\$120.00
2-10 20089	Condensate Pump	\$119.00
2-10 20564	Pump Ups (set of four) - Condensing Unit	\$125.50
2-10 20575	Refrigerant Recovery & Reclaim	\$58.00
2-10 20591	Disconnect - Condensing Unit	\$57.29
2-10 20598	Locking Service Valve Caps (Pair)	\$33.00
2-10 20641	Ductwork Transition Supply Plenum	\$158.00
2-10 20642	Ductwork Transition Return Plenum	\$158.00
2-10 20712	Extra Man / Helper (additional labor only)	\$20.00
2-10 20802	HVAC – Minor Component Installation Labor (Does not include materials)	\$100.00
2-10 20803	HVAC – Major Component Installation Labor (Does not include materials)	\$150.00
2-10 20805	HBW Supplied Line Set Install (410A Conversion Surcharge)	\$50.00
2-10 20821	No Repair / No Problem / Buy-Out Visit / NLA Part Install	\$65.00
2-10 20831	Non-Covered Repair Visit	\$65.00
BELT-BEJA-0030	Adjust Drive Belt - This service is for tensioner and sheave adjustment only with existing belt. Drive belts should be replaced and adjusted annually. Improper adjustments or lack of maintenance can cause premature wear of pulleys sheaves and motor bear	\$120.75
BELT-BELT-0020	Replace Drive Belt - Includes tensioner and sheave adjustment. Drive belts should be replaced and adjusted annually. Improper adjustments or lack of maintenance can cause premature wear of pulleys sheaves and motor bearings in addition to complete failu	\$141.07
BELT-PARTS-0020	Replace Belt Drive Parts - 1-Year Parts & Labor Warranty. This service is for replacing components for a belt drive assembly such as sheaves pulleys bearings tensioners etc. A replacement drive belt is often needed with this service and should be rep	\$284.95
BELT-WHEL-0060	Replace OEM Blower Motor - 1-Year Parts & Labor Warranty. Includes new capacitor if motor is PSC type. Variable speed and ECMs may require a replacement motor module.	\$357.02
BOIL-AIRV-0030	Replace Hydronic Air Vent - 1-Year Parts & Labor Warranty. Automatic air purge vents are necessary for removing air that is naturally dissolved in water in your hydronic system. Air vent seals do leak with age and often need replacing regularly. This ser	\$178.55
BOIL-AQUA-0045	Replace Boiler Aquastat - 1-Year Parts & Labor Warranty. This service is for replacing an aquastat on a boiler. Aquastat may be vertical or horizontal orientation include a vent damper relay or have both low and high limit thermostats. Customer is advis	\$762.55

Name	Sales Desc	Price
BOIL-BLEED-0030	Bleed Hydronic System - No warranty on service. This service is for bleeding one or more radiators convectors or water coils that may be air-locked. Customer is advised not all hydronic systems allow for success in removing air from these components and	\$44.42
BOIL-CIRC-0060	Replace Hydronic Circulator - 1-Year Parts & Labor Warranty. This service is for replacing a circulator for a hydronic system. Replacement part may be cartridge only or full body replacement. Customer is advised the hydronic system may need to be drained	\$507.96
BOIL-DRAI-0090	Drain Refill and Purge Air from Hydronic System - This service is for draining down and refilling a boiler or hydronic system for repairs. Customer is advised as pressure is relieved from system and re-pressurized seals can often fail due to age and le	\$260.42
BOIL-EXPT-0045	Replace Boiler Expansion Tank - 1-Year Parts & Labor Warranty. This service is for replacing any expansion tank for a boiler up to 5 gallon capacity. The expansion tank is critical in allowing water to expand inside a hydronic system without stressing pa	\$290.74
BOIL-FILLV-0060	Replace Fill Valve - 1-Year Parts & Labor Warranty. This service is for replacing a fill valve or pressure reducing valve on a hydronic system. Pricing may include a backflow preventer which is often required and should be replaced at time of this serv	\$5.22
BOIL-LWCO-0045	Install/Replace Low Water Cut-Off - 1-Year Parts & Labor Warranty. This service is for installing a new or replacing an existing low water cut-off (LWCO) device for a hydronic system and may not include draining refilling and bleeding system. LWCOs are	\$511.40
BOIL-MISC-0060	Replace Boiler Part - 1-Year Parts & Labor Warranty. This service is for replacing any proprietary or generic boiler part. Customer is advised part must be replaced prior to fully operating boiler and additional repairs may be required. Customer is advise	\$443.60
BOIL-PRV-0030	Replace Pressure Relief Valve (30 PSI) - 1-Year Parts & Labor Warranty. This service is for replacing a pressure relief valve (PRV) on a low pressure hydronic system. Customer is advised PRVs can fail for numerous reasons including but not limited to an	\$234.60
BOIL-ZONE-0030	Replace Hydronic Zone Actuator/Valve - 1-Year Parts & Labor Warranty. This service is for replacing an automatic zone actuator and may include a new valve if required. If zone valve is required to be replaced the hydronic system will need to be drained	\$425.70
CAP-0255-0030	Non-OEM 25/5 MFD Dual Run Capacitor - 1-Year Parts & Labor Warranty. Run capacitors are designed to provide motors with enough torque to rotate at designed speed. A weak or failed capacitor may prevent the motor from operating at the correct speed or star	\$197.87
CAP-0305-0030	Non-OEM 30/5 MFD Dual Run Capacitor - 1-Year Parts & Labor Warranty. Run capacitors are designed to provide motors with enough torque to rotate at designed speed. A weak or failed capacitor may prevent the motor from operating at the correct speed or star	\$199.60

Name	Sales Desc	Price
CAP-0355-0030	Non-OEM 35/5 MFD Dual Run Capacitor - 1-Year Parts & Labor Warranty. Run capacitors are designed to provide motors with enough torque to rotate at designed speed. A weak or failed capacitor may prevent the motor from operating at the correct speed or star	\$199.25
CAP-0405-0030	Non-OEM 40/5 MFD Dual Run Capacitor - 1-Year Parts & Labor Warranty. Run capacitors are designed to provide motors with enough torque to rotate at designed speed. A weak or failed capacitor may prevent the motor from operating at the correct speed or star	\$200.68
CAP-0455-0030	Non-OEM 45/5 MFD Dual Run Capacitor - 1-Year Parts & Labor Warranty. Run capacitors are designed to provide motors with enough torque to rotate at designed speed. A weak or failed capacitor may prevent the motor from operating at the correct speed or star	\$201.50
CAP-0505-0030	Non-OEM 50/5 MFD Dual Run Capacitor - 1-Year Parts & Labor Warranty. Run capacitors are designed to provide motors with enough torque to rotate at designed speed. A weak or failed capacitor may prevent the motor from operating at the correct speed or star	\$215.89
CAP-0555-0030	Non-OEM 55/5 MFD Dual Run Capacitor - 1-Year Parts & Labor Warranty. Run capacitors are designed to provide motors with enough torque to rotate at designed speed. A weak or failed capacitor may prevent the motor from operating at the correct speed or star	\$203.82
CAP-HARD-0030	Super Boost Compressor Hard Start Kit - 1-Year Parts & Labor Warranty. Start capacitors are used to provide motors with high starting torque and some but not all compressors require start capacitors. This may be used as a replacement factory start capac	\$230.60
CAP-MINI-0030	AmRad Turbo Mini Capacitor - 1-Year Parts & Labor Warranty - Run capacitors are designed to provide motors with enough torque to rotate at designed speed. A weak or failed capacitor may prevent the motor from operating at the correct speed or starting at	\$214.81
CAP-TURBO-0030	AmRad Turbo 200 Run Capacitor - 1-Year Parts & Labor Warranty 5-Year Parts Warranty - This is a high performance capacitor designed and manufactured for extreme use and may be configured to match various specifications. This part is appropriate for situa	\$328.22
CLEA-COIL-0075	Clean Indoor Coil - This service is for cleaning an indoor coil while in place. Does not require removal of coil. Customer is advised to have regular preventative maintenance performed to keep system operating properly and safely.	\$220.00
CLEA-COND-0030	Clean Outdoor Coil - Chemically clean coil remove debris from base pan and coil guards. Customer is advised to have regular preventative maintenance performed to keep system operating properly and safely.	\$104.00
CLEA-EVRE-0060	Clean Indoor Coil - This service is for cleaning an indoor coil that requires extraction of coil. Customer is advised to have regular preventative maintenance performed to keep system operating properly and safely.	\$295.94

Name	Sales Desc	Price
CLEA-FLUS-0030	Flush and Clear Primary Drain Line - This repair has no warranty. Drain line obstructions can occur from improperly sloped drain lines excessive condensation algae blooms dust and debris etc. Regular maintenance is critical to prevent future blockages	\$84.00
CLEA-WHEL-0050	Remove and Clean Blower Wheel and Housing - Requires extracting blower assembly and removing blower motor from hub. This action may require additional labor if motor shaft is corroded or seized. Customer is advised of preventative maintenance and replace	\$140.00
COEV-2PVC-0020	Replace PVC or CPVC Fittings (up to 3/4") - This service is for repairing or replacing PVC or CPVC drain lines up to 3/4" diameter. May require additional materials or labor depending on scope of work.	\$121.10
COEV-4PVC-0030	Replace PVC or CPVC Fittings (1"-3") - This service is for repairing or replacing PVC or CPVC between 1" and 3" in diameter such as drain lines or flue piping. May require additional materials or labor depending on scope of work.	\$196.57
COEV-COLL-0060	Replace OEM Collector Box for 90%+ AFUE Gas Furnace - 1-Year Parts & Labor Warranty. Customer is advised underlying issues may exist and may not be fully known until this part is replaced and additional repairs may be necessary. Customer is advised to hav	\$291.02
COEV-EZT6-0030	Install EZ Trap and Test Operation - 1-Year Parts & Labor Warranty. Includes a drain line overflow safety switch that is designed to shut your system off in the event of a draining issue or blockage to help prevent water damage.	\$162.93
COEV-PANS-0030	Install Drain Pan Overflow Safety - 1-Year Parts & Labor Warranty. AquaGuard AG-1100 overflow safety switch or equivalent for drain pans. This safety switch is designed to shut off your system in the event of a water drainage problem or obstruction to hel	\$124.87
COEV-PUMP-0045	Install Condensate Pump with Internal Overflow Safety - 1-Year Parts & Labor Warranty. Install or replace 115/230 VAC condensate pump either standard or low-profile. Service may include new vinyl tubing drain line restructuring or electrical outlet if	\$338.26
COEV-SS2-0030	Install Drain Line Overflow Safety - 1-Year Parts & Labor Warranty. Rectorseal SS2 overflow safety switch or equivalent for drain lines. This safety switch is designed to shut off your system in the event of a water drainage problem or obstruction to help	\$142.81
COEV-TREAT-0030	Apply Condensate Treatment - This service is for applying treatment for a condensate drain line or drain pan such as algaecide tablets disinfectant or simply clean out debris. Customer is advised to have regular preventative maintenance performed to pr	\$86.42
COM-0001-0090	Replace OEM Compressor - 1-Year Parts & Labor Warranty. Includes new start components and filter drier as required. Customer is advised compressor failures can be caused by poor airflow low or high refrigerant charge metering issues excessive runtime	\$1,919.67
Commercial Service Repair	Need to add description	\$4.50

Name	Sales Desc	Price
COMP-CCH-0030	Replace/Install Crankcase Heater - 1-Year Parts & Labor Warranty. This service is to replace an existing or install a new crankcase heater on any residential compressor. Crankcase heaters work by keeping the base of the compressor warm enough to prevent l	\$364.05
COMP-COOL-0030	Cool Down Overheated Compressor - Customer is advised primary issue of compressor overheating may not be known until system is fully operational. Repeated incidents of overheating may damage compressor or reduce expected lifespan.	\$84.00
COMP-DEFR-0030	De-ice Indoor or Outdoor Coil - Customer is advised primary issue may not be known until coil is fully de-iced and system operating fully.	\$84.00
COMP-PLUG-0030	Replace Compressor Plug - 1-Year Parts & Labor Warranty. This service is for replacing a compressor plug and wiring. Customer is advised this is a critical part and must be replaced prior to testing and operating the system fully. An underlying issue may	\$387.00
COM-WARR-0060	Replace Warranty OEM Compressor - 1-Year Parts & Labor Warranty. Includes new start components and filter drier as required. Customer is advised compressor failures can be caused by poor airflow low or high refrigerant charge metering issues excessive	\$1,209.47
CONT-BOAR-0045	Replace OEM Control Board - 1-Year Parts & Labor Warranty. This is a critical part. Customer is advised underlying issues may exist and may not be fully known until this part is replaced and additional repairs may be necessary. Customer is advised to have	\$268.37
CONT-TRAN-0045	Replace 40VA Step-Down Transformer - 1-Year Parts & Labor Warranty	\$304.27
Custom Service	Need to add description of task performed	\$1.00
Custom Service 2	Used for addition Custom Service with a different price	\$1.00
Custom Service 3	Used for addition Custom Service with a different price	\$1.00
Custom Service 4	Used for addition Custom Service with a different price	\$1.00
DCT-ACTU-0060	Replace Zone Actuator - 1-Year Parts & Labor Warranty. This service is for replacing an automatic zone actuator such as Honeywell or Aprilaire but may not including the damper. Customer is advised to have regular preventative maintenance performed and in	\$471.60
DCT-BALANCE-0120	Balance & Test Duct System - This service is for testing airflow at every accessible supply and return grille with use of a flow hood which is useful in verifying airflow to one or more rooms after adjusting dampers. Duct work will be balanced according	\$501.60
DCT-DAMPER-0060	Replace/Install Air Dampers - 1-Year Parts & Labor Warranty. This service is for replacing one or more existing or adding new air dampers. Technician will specify type of damper to be installed such as parallel or opposed-blade round or square. Customer	\$245.11
DCT-FLUE-0030	Replace/Repair Flue Pipe (80% AFUE or less) - 1-Year Parts & Labor Warranty. This service is for replacing single-wall B-vent or stainless-steel B-vent flue pipe up to 8" diameter.	\$10.88

Name	Sales Desc	Price
DCT-REPAIR-0060	Repair Duct Work (Minor) - This service is for a repair on duct work requiring minimal materials such as reconnecting a broken duct adding supports re-routing a duct or sealing air leaks. Customer is advised to have regular preventative maintenance pe	\$155.42
DCT-REPAIR-0120	Repair Duct Work (Major) - This service is for a repair on duct work that requires additional materials such as replacing a broken or collapsed duct adding a duct or upsizing a duct. Customer is advised to have regular preventative maintenance performe	\$308.42
DCT-SEAL-0060	Seal Equipment / Duct Air Leaks - This service is for sealing air gaps found on air handlers furnaces cased coils plenums duct collars or any other air leaks found by technician. This service often requires minimum materials but may require mastic s	\$181.16
ELECT-0003-0005	3-amp ATC Fuse - Fuse replacement only. Customer is advised to allow technician to identify electrical fault to prevent fuse from blowing in future.	\$34.47
ELECT-0005-0005	5-amp ATC Fuse - Fuse replacement only. Customer is advised to allow technician to identify electrical fault to prevent fuse from blowing in future.	\$35.07
ELECT-0015-0005	15-amp FRN Fuse - Fuse replacement only. Customer is advised to allow technician to identify electrical fault to prevent fuse from blowing in future.	\$45.10
ELECT-0020-0005	20-amp FRN Fuse - Fuse replacement only. Customer is advised to allow technician to identify electrical fault to prevent fuse from blowing in future.	\$45.10
ELECT-0025-0005	25-amp FRN Fuse - Fuse replacement only. Customer is advised to allow technician to identify electrical fault to prevent fuse from blowing in future.	\$45.62
ELECT-0030-0005	30-amp FRN Fuse - Fuse replacement only. Customer is advised to allow technician to identify electrical fault to prevent fuse from blowing in future.	\$45.10
ELECT-0035-0005	35-amp FRN Fuse - Fuse replacement only. Customer is advised to allow technician to identify electrical fault to prevent fuse from blowing in future.	\$51.77
ELECT-0040-0005	40-amp FRN Fuse - Fuse replacement only. Customer is advised to allow technician to identify electrical fault to prevent fuse from blowing in future.	\$51.77
ELECT-0045-0005	45-amp FRN Fuse - Fuse replacement only. Customer is advised to allow technician to identify electrical fault to prevent fuse from blowing in future.	\$51.77
ELECT-0060-0005	60-amp FRN Fuse - Fuse replacement only. Customer is advised to allow technician to identify electrical fault to prevent fuse from blowing in future.	\$52.57
ELECT-BATT-0015	Replace Generator Battery - 1-Year Parts & Labor Warranty. This service is for replacing a generator battery. Service may include replacement battery connectors if required. Includes returning defective battery for recycling. Customer is advised this is	\$225.70

Name	Sales Desc	Price
ELECT-BREA-0045	Replace Single or Two-Pole Residential Breaker - 1-Year Parts & Labor Warranty. Breakers serve to disconnect power to the circuit when current draw exceeds the rating of the breaker. Breakers commonly weaken and wear with time but underlying issues may e	\$321.37
ELECT-DI15-0045	Install 115 VAC Single-Pole Switch - 1-Year Parts & Labor Warranty. Service to install or replace an existing 115 VAC switch commonly used for disconnecting gas equipment or other appliance. Customer may opt for a decor switch at additional cost.	\$155.62
ELECT-DI30-0045	Install 30-amp Fused Service Disconnect - 1-Year Parts & Labor Warranty. May not include conduit or electrical materials unless specified. Disconnect will be fused to match the maximum ampacity rating as indicated on the equipment.	\$320.18
ELECT-DI60-0045	Install 60-amp Fused Service Disconnect - 1-Year Parts & Labor Warranty. May not include conduit or electrical materials unless specified. Disconnect will be fused to match the maximum ampacity rating as indicated on the equipment.	\$325.95
ELECT-SHOR-0060	Locate Electrical Fault - Service to locate an electrical fault in low or high voltage wiring. If applicable customer is advised fuses should not be replaced or breakers reset if tripped until integrity of the circuit is verified and underlying issue ide	\$168.00
ELECT-TEST-0015	Reset Equipment and Test - This service is necessary to verify safe conditions to operate and fully test equipment if locked out by a safety control. Declining this service will void 30-Day Warranty on diagnostic.	\$42.00
ELECT-WHIP-0025	Replace 6' of Liquid-Tight Conduit (up to 3/4" diameter)	\$197.37
ELECT-WIRE-0020	Wiring Repair (Minor) - This service is for repairing low or high voltage wiring that may require minimal materials or labor.	\$53.42
ELECT-WIRE-0045	Wiring Repair (Standard) - This service is for repairing low or high voltage wiring that may require standard materials or labor.	\$127.42
ELECT-WIRE-0060	Wiring Repair (Major) - This service is for repairing low or high voltage wiring that may require significant materials or labor.	\$169.42
ELEH-0003-0030	Heat Sequencer (2-Stack 2-Poles 24A34-3) - 1-Year Parts & Labor Warranty	\$207.44
ELEH-0006-0030	Heat Sequencer (2-Stack 4-Poles 25A34-6) - 1-Year Parts & Labor Warranty	\$225.94
ELEH-FUSL-0020	Replace Fusible Link(s) - 1-Year Parts & Labor Warranty. This service is for replacing one or more fusible links on a heater kit. Customer is advised an underlying issue may exist that caused the fusible links to fail such as poor airflow. Customer is ad	\$224.52
ELEH-HEATK-0045	Replace Heater Kit - 1-Year Parts & Labor Warranty. This service is for replacing a factory heater kit of any size. Customer is advised an underlying issue may exist that caused the heater kit to fail such as poor airflow. Customer is advised to address	\$352.15



Name	Sales Desc	Price
GASH-ADJS-0025	Adjust and Inspect Burners - Includes removing burners of any type that allows reasonable access. Excessive dust and corrosion can cause interruption in operation reduced efficiency and CO poisoning or fire in extreme situations. Customer is advised to	\$149.17
GASH-BUR2-0005	Replace Gas Burner Each Additional - 1-Year Parts & Labor Warranty	\$30.97
GASH-BURN-0030	Replace Gas Burner - 1-Year Parts & Labor Warranty. Service for replacing worn or damaged burners. Excessive dust and corrosion can cause interruption in operation reduced efficiency and CO poisoning or fire in extreme situations. Customer is advised to	\$208.72
GASH-CA-0060	Combustion Analysis - This service is for performing a combustion analysis on one gas or oil-fired appliance. A combustion analysis is important to determine the efficiency and safe operation of a fossil-fuel appliance. This is generally recommended when	\$442.35
GASH-CLEN-0015	Clean and Test Flame Sensor - Flame sensors require regular cleaning for proper operation. Customer is advised to have preventative maintenance performed regularly to prevent fouling of flame sensor and keep gas appliance operating properly and safely.	\$86.42
GASH-CLEN-0045	Inspect and Relight Pilot - Service is for standing pilot assemblies and assumes reasonable access. Customer is advised there may be an underlying issue regarding the pilot extinguishing and cannot be verified until this service is performed. Customer is	\$127.42
GASH-CO2-0020	Install Carbon Monoxide Detector - 1-Year Parts & Labor Warranty. Customer is advised to have preventative maintenance performed on gas appliances regularly for safety and correct operation.	\$160.46
GASH-DOOR-0300	Replace OEM Interlock/Door Switch - 1-Year Parts & Labor Warranty	\$268.72
GASH-EXCH-0300	Replace OEM Primary and/or Secondary Heat Exchanger - 1-Year Parts & Labor Warranty. Includes all gaskets and materials necessary for service. Customer is advised heat exchangers can warp or crack due to but not limited to age poor airflow excessive moi	\$2,479.42
GASH-EXWR-0300	Replace Warranty OEM Primary and/or Secondary Heat Exchanger - 1-Year Parts & Labor Warranty. Includes all gaskets and materials necessary for service. Customer is advised heat exchangers can warp or crack due to but not limited to age poor airflow exce	\$1,829.42
GASH-FIRE-0030	Replace/Install Part for Gas Fireplace - 1-Year Parts & Labor Warranty - This service is for replacing or installing one or more parts on a gas fireplace such as ignition modules oxygen depletion sensors blowers thermopiles etc. Customer is advised u	\$223.45
GASH-FLSE-0030	Replace Flame Sensor - 1-Year Parts & Labor Warranty. Customer is advised underlying issues may exist and may not be fully known until this part is replaced and additional repairs may be necessary. Customer is advised to have preventative maintenance perf	\$213.72



Name	Sales Desc	Price
GASH-IGN-0030	Replace non-OEM Hot Surface Ignitor - 1-Year Parts & Labor Warranty. This is a silicon nitride hot surface ignitor that replaces many OEM ignitors so long as supply voltage is 120 VAC. Customer is advised underlying issues may exist and may not be fully k	\$288.52
GASH-IGN-0045	Replace OEM Ignitor (HSI or Spark Rod) - 1-Year Parts & Labor Warranty. This service is for replacing the factory ignitor on a gas appliance where a generic ignitor cannot be installed. Customer is advised underlying issues may exist and may not be fully	\$263.50
GASH-INDU-0060	Replace Inducer/Combustion Blower Assembly - 1-Year Parts & Labor Warranty. Customer is advised underlying issues may exist and may not be fully known until this part is replaced and additional repairs may be necessary. Customer is advised to have prevent	\$756.02
GASH-LIMIT-0030	Replace Safety Limit - 1-Year Parts & Labor Warranty. A failed safety device may indicate an underlying issue. Customer is advised additional issues may exist and may not be fully known until this part is replaced and additional repairs may be necessary.	\$353.72
GASH-LITE-0015	Re-Light Standing Pilot and Observe - No warranty on this service. Standing pilots may extinguish for various reasons outside our control such as drafts intermittent gas service etc. Technician will observe pilot and identify any underlying issues to th	\$43.42
GASH-OEMI-0030	Replace OEM Hot Surface Ignitor - 1-Year Parts & Labor Warranty. Customer is advised underlying issues may exist and may not be fully known until this part is replaced and additional repairs may be necessary. Customer is advised to have preventative maint	\$383.72
GASH-PRESS-0030	Replace non-OEM Draft Pressure Switch - 1-Year Parts & Labor Warranty. This part replaces most draft pressure switches without issue. Customer is advised underlying issues may exist and may not be fully known until this part is replaced and additional rep	\$280.12
GASH-PRESS-0045	Replace OEM Draft Pressure Switch - 1-Year Parts & Labor Warranty. This is the replacement factory draft pressure switch. Customer is advised underlying issues may exist and may not be fully known until this part is replaced and additional repairs may be	\$263.50
GASH-THERM-0030	Replace Thermocouple - 1-Year Parts & Labor Warranty. This part is critical in that it powers the gas valve for the appliance. Customer is advised underlying issues may exist and may not be fully known until this part is replaced and additional repairs ma	\$199.51
GASH-THP-0030	Replace Thermopile - 1-Year Parts & Labor Warranty. This part is critical in that it powers the gas valve for the appliance. Customer is advised underlying issues may exist and may not be fully known until this part is replaced and additional repairs may	\$328.49
GASH-VAL1-0060	Replace OEM Gas Valve - 1-Year Parts & Labor Warranty. Includes installation leak testing gas fittings and testing. Customer is advised underlying issues may exist and may not be fully known until this part is replaced and additional repairs may be nece	\$761.02

Name	Sales Desc	Price
GASH-VALV-0060	Replace non-OEM Gas Valve - 1-Year Parts & Labor Warranty. This part replaces many OEM gas valves without issue. Includes installation leak testing gas fittings and testing. Customer is advised underlying issues may exist and may not be fully known until	\$664.50
GASP-FLEX-0030	Install Flexible Gas Connector (up to 3/4" diameter) - 1-Year Parts & Labor Warranty. Customer is advised to have preventative maintenance performed to keep gas appliance operating properly and safely.	\$246.92
GASP-LEK1-0045	Gas Leak Search - This service is used to investigate a possible gas leak observed by the customer or technician. All accessible gas piping in the suspected area of the leak. A comprehensive leak search of all gas piping in the home or building is optional	\$126.00
GASP-PIP1-0060	Replace up to Four (4) 1/2" Black Iron Gas Fittings	\$135.40
GASP-PIP2-0060	Replace 3/4" Black Iron Gas Fitting(s)	\$135.40
GASP-VALV-0030	Replace Gas Shut-Off Valve	\$203.80
HPR-DEFB-0030	Install Universal Defrost Board - 1-Year Parts & Labor Warranty. This service is for replacing an existing defrost board with a universal defrost board. Customer is advised this replacement may have several benefits over the OEM replacement part: (1) the	\$389.86
HPR-HAIL-0030	Install/Replace OEM Hail Guard - 1-Year Parts & Labor Warranty. This service is for installing or replacing a hail guard for an outdoor unit. Hail guards help protect outdoor coils from damaging ice and hail which can greatly affect performance and reduce	\$4.97
HPR-INSU-0015	Replace up to 5' ArmaFlex or Equivalent Pipe Insulation - 1-Year Parts & Labor Warranty. Pipe insulation degrades with time when exposed to sunlight weather moisture and extreme conditions. Pipe insulation is recommended to keep the system performing a	\$58.42
HPR-RISE-0050	Install 3" Risers at Outdoor Unit - 1-Year Parts & Labor Warranty. Risers are recommended to not only keep the outdoor unit above average snowline but allow water to drain away from the unit as quickly as possible to prevent corrosion of the outdoor coil	\$175.06
HPR-SENS-0030	Replace Sensor - 1-Year Parts & Labor Warranty. Replacement coil thermistor ambient sensor or snap-action coil sensor.	\$288.72
HPR-VALV-0060	Replace Reversing Valve - 1-Year Parts & Labor Warranty. Customer is advised reversing valves can seize for many reasons not limited to debris circulating in refrigeration system. All refrigerant must be recovered but this action may not remove all debris	\$929.20
HPR-WRVA-0060	Replace Reversing Valve (OEM Warranty) - 1-Year Parts & Labor Warranty. Customer is advised reversing valves can seize for many reasons not limited to debris circulating in refrigeration system. All refrigerant must be recovered but this action may not	\$1,546.09

Name	Sales Desc	Price
IAQ-BLUE-0045	Install Fresh-Aire Blue-Tube Germicidal UV Light - 1-Year Parts & Labor Warranty. Service for installing a Blue-Tube germicidal UV light in HVAC equipment or duct work. UV lights are designed to inhibit biological growth in the air and on surfaces. Manufa	\$643.61
IAQ-BULB-0015	Replacement UV Bulb/PHI Cell - 1-Year Parts & Labor Warranty. This service is for providing a replacement UV bulb and/or PHI cell for indoor air quality device. These components are generally recommended to be replaced every 2-3 years depending on the ma	\$110.70
IAQ-FILT-0010	Replacement Media Filter - This service is for providing a replacement whole-home media filter whether Aprilaire Honeywell or a generic brand. Whole-home media filters are generally required to be replaced every 6-12 months but may vary depending on t	\$150.24
IAQ-FILT-0012	Replacement Air Filter - This service is for providing a replacement 1" air filter. Price may be adjusted to account for multiple filters such as an annual supply. 1" air filters are recommended to be replaced every 30-60 days but may vary depending on	\$92.04
IAQ-FILT-0013	Replacement Air Filters (Commercial) - This service is for providing replacement filters for a commercial property. Customer is advised filters should be replaced quarterly and systems maintained at least annually for proper and safe operation.	\$106.35
IAQ-HUM-0010	Replace Water Panel - This service is for providing and replacing a humidifier water panel for any residential evaporative humidifier. Water panels are recommended to be replaced annually to prevent the growth of mold.	\$151.44
IAQ-HUMC-0010	Replace Aprilaire 800 Canister - This service is for providing and replacing a water canister with electrodes for the Aprilaire 800 Steam Humidifier. Water canister is recommended to be replaced annually to prevent scale build-up and deterioration of O-ri	\$309.54
IAQ-WAVE-0045	Install Nu-Calgon iWave-R - 1-Year Parts & Labor Warranty. The iWave is an air purifying device that installs in any duct air conditioning system. When air passes over the iWave ions produced by the device reduce pathogens allergens particles smoke	\$813.00
MOT-BL01-0075	Replace non-OEM 115 VAC 1075 RPM PSC Blower Motor - 1-Year Parts & Labor Warranty. Includes new mini Turbo run capacitor. Also includes extraction of blower assembly mounting and balancing new motor and adjusting airflow settings. Mounting bracket may b	\$679.48
MOT-BLMO-005	Install Universal Blower Motor Mounting Bracket - 1-Year Parts & Labor Warranty. Use where a new mounting bracket is required.	\$30.97
MOT-COND-0075	Replace non-OEM 208-230 VAC 1075 RPM PSC Outdoor Fan Motor - 1-Year Parts & Labor Warranty. Includes new mini Turbo run capacitor. Also includes extraction of defective motor mounting and balancing new motor and adjusting airflow settings. Customer is a	\$668.65

Name	Sales Desc	Price
MOT-MOUNT-0045	Replace Motor Mounting Bracket Only - 1-Year Parts & Labor Warranty. Requires adjusting and balancing motor. This service does not include a new blower motor.	\$339.43
MOT-OEM1-0060	Replace OEM ECM Blower or Outdoor Fan Motor - 1-Year Parts & Labor Warranty. Service for manufacturer ECM or variable-speed motors. Includes extraction of defective motor mounting and balancing new motor and adjusting airflow settings. Customer is advis	\$637.11
MOT-PART-0045	Replace Motor Parts - 1-Year Parts & Labor Warranty. This service is for replacing one or more parts needed for an outdoor or indoor motor such as housing wheel bearings etc. Customer is advised these parts may need to be replaced prior to fully testi	\$354.70
MOT-WARR-0060	Replace OEM PSC Blower or Outdoor Fan Motor - 1-Year Parts & Labor Warranty. Service for manufacturer PSC motors. Includes new mini Turbo run capacitor. Includes extraction of defective motor mounting and balancing new motor and adjusting airflow settin	\$503.11
MOT-X130-0060	Replace Universal Evergreen ECM Blower Motor - 1-Year Parts & Labor Warranty. Service for non-OEM ECM blower motor. Includes extraction of defective motor mounting and balancing new motor and adjusting airflow settings. Customer is advised underlying is	\$674.93
OIL-CADC-0030	Replace Cadmium Cell - 1-Year Parts & Labor Warranty. Cad cells can become less effective with time and eventually require replacing but properly functioning cad cells do require regular cleaning. Customer is advised underlying issues may exist and may n	\$298.72
OIL-CONT-0045	Replace Primary Control for Oil Burner - 1-Year Parts & Labor Warranty. Replace existing primary control with a solid-state primary control. Customer is advised underlying issues may exist and may not be fully known until this part is replaced and additio	\$448.37
OIL-NOFL-0030	Replace Oil Nozzle and Filter - No warranty as parts are subject to fouling from fuel oil. ***These parts should be replaced annually*** Customer is advised underlying issues may exist and may not be fully known until this part is replaced and additional	\$217.70
OIL-NOZZ-0020	Replace Oil Nozzle Only - No warranty as parts are subject to fouling from fuel oil. Oil filter is highly recommended to be replaced with a new nozzle unless noted otherwise. ***These parts should be replaced annually*** Customer is advised underlying is	\$139.00
OIL-TRAN-0045	Replace Step-Up Transformer for Oil Burner - 1-Year Parts & Labor Warranty. Replaces existing transformer with a solid-state transformer that produces at least 14 000 volts. Customer is advised underlying issues may exist and may not be fully known until	\$403.37
PRW-ANGLEV-0030	Replace Angle Valve - 1-Year Parts & Labor Warranty. This service is for replacing an angle valve such as for a toilet or sink. Customer is advised this service may require turning water valves off which if not regularly exercised may begin leaking when	\$130.60

Name	Sales Desc	Price
PRW-EXPT-0045	Install/Replace Expansion Tank - 1-Year Parts & Labor Warranty. This service is for replacing or installing an expansion tank commonly found on water heaters. Customer is advised this service may require turning water valves off which if not regularly ex	\$283.99
PRW-FILLV-0045	Replace Toilet Fill Valve - 1-Year Parts & Labor Warranty. This service is for replacing a fill valve assembly on any toilet which includes new fill valve flapper and chain. Customer may opt for the OEM part if desired. Customer is advised this servic	\$163.45
PRW-FILTER-0020	Replace Whole-Home Water Filter - 1-Year Parts & Labor Warranty. This service is for replacing an existing whole-home water filter with a new filter. Customer is advised this service may require turning water valves off which if not regularly exercised m	\$108.70
PRW-GARBD-0045	Replace Garbage Disposal - 1-Year Parts & Labor Warranty. This service is for replacing a garbage disposal of equal or greater horsepower. Includes hook-up to dishwasher (if available) and testing.	\$386.45
PRW-HAMM-0045	Install Water Hammer Arrestor - 1-Year Parts & Labor Warranty. This service is for installing a water hammer arrestor on a residential plumbing system. Hammer arrestors are crucial to reduce mechanical stress on plumbing fixtures when experiencing rapid c	\$196.30
PRW-HOSEB-0030	Replace Hose Bib - 1-Year Parts & Labor Warranty. This service is for replacing one or more hose bibs. Customer may opt for a frost-free hose bib if desired. Customer is advised this service may require turning water valves off which if not regularly ex	\$167.95
PRW-PLUMR-0015	Plumbing Repair (Minor) - This service is for repairing a plumbing issue with minimal materials such as clearing a drain torquing a fitting etc. Customer is advised to have accessible plumbing fixtures inspected annually to mitigate property damage cau	\$35.27
PRW-PLUMR-0030	Plumbing Repair (Major) - This service is for repairing a plumbing issue requiring additional materials such as fittings replacing sections of pipe mixing valves etc. Customer is advised this service may require turning water valves off which if not	\$332.07
PRW-PRV-0015	Replace Pressure Relief Valve (High Pressure) - 1-Year Parts & Labor Warranty. This service is for replacing a pressure relief valve (PRV) found on a water heater or similar appliance except for low pressure boilers. Customer is advised this service may	\$162.15
PRW-SHUTOFF-0015	Replace/Install Water Shut-Off Valve - 1-Year Parts & Labor Warranty. This service is for replacing an existing or installing a new water shut-off valve. Customer is advised this service may require turning water valves off which if not regularly exercis	\$130.60
PRW-SINKPART-0045	Replace Sink Parts - 1-Year Parts & Labor Warranty. This service is for replacing parts on a sink whether OEM or generic.	\$97.75

Name	Sales Desc	Price
PRW-SINKPO-0045	Replace Sink Pop-Up Drain - 1-Year Parts & Labor Warranty. This service is for replacing a sink pop-up drain. Customer may opt for the OEM part if desired. Customer is advised this service may require turning water valves off which if not regularly exer	\$171.34
PRW-SINKPT-0045	Replace Sink P-Trap Assembly - 1-Year Parts & Labor Warranty. This service is for replacing a P-trap assembly found on most residential sinks.	\$171.34
PRW-TOILET-0045	Replace Toilet - 1-Year Parts & Labor Warranty. This service is for replacing a toilet which may include a new wax ring. Customer is advised this service may require turning water valves off which if not regularly exercised may begin leaking when operat	\$414.70
PRW-TOILP-0045	Replace Toilet Part(s) - 1-Year Parts & Labor Warranty. This service is for replacing parts on a toilet that may be proprietary such as toilet seat handle reservoir cover etc.	\$86.80
REFC-AR220-0015	Add HCFC R22 (per pound) - No warranty on refrigerant. Customer is advised HCFC R22 refrigerant has been phased-out since January 2020 and is no longer in production. There are many causes for refrigerant leaks including but not limited to vibration cor	\$165.02
REFC-AR410-0015	Add HFC R410A (per pound) - No warranty on refrigerant. There are many causes for refrigerant leaks including but not limited to vibration corrosive environments and stress fractures from thermal expansion. Less refrigerant than required results in red	\$108.45
REFC-AR44B-0015	Add R22 Retrofit Refrigerant (per pound) - No warranty on refrigerant or claims of performance. Customer is advised HCFC R22 refrigerant has been phased-out since January 2020 and is no longer in production. Retrofit refrigerants are approved for use in R	\$213.87
REFC-CAPS-0015	Install Refrigerant Locking Caps on Service Ports - 1-Year Parts & Labor Warranty. Locking caps help prevent refrigerant from escaping service ports as well as allow only qualified service professionals to service your system. These are required by code i	\$84.42
REFC-COIL-0060	Replace Indoor or Outdoor Coil - 1-Year Parts & Labor Warranty. Service for replacing indoor or outdoor coil for equipment not under manufacturer warranty. Includes extraction of defective coil and installing replacement part brazing connections and rec	\$357.02
REFC-COILW-0060	Replace Indoor or Outdoor Coil (OEM Warranty) - 1-Year Parts & Labor Warranty. Service for replacing indoor or outdoor coil for equipment with a manufacturer warranty. Includes extraction of defective coil and installing replacement part brazing connecti	\$430.02
REFC-CORE-0015	Replace Valve Core in Service Port - 1-Year Parts & Labor Warranty - Replacement valve core for service port. Valve cores can wear with time often require replacing with use.	\$93.57
REFC-DYE1-0015	Inject Ultraviolet Dye for Leak Detection - No warranty on procedure or refrigerant. Ultraviolet dye is recommended for systems with refrigerant leaks not easliy detected by other means. Ultraviolet dye may remain in the refrigeration system for the life	\$155.88

Name	Sales Desc	Price
REFC-LEAK-0090	Electronic Refrigerant Leak Search - No warranty on procedure or refrigerant. Electronic leak searches are effective at locating active refrigerant leaks where the leak is easily accessible. Repeated refrigerant loss with no positive feedback from electro	\$253.00
REFC-LSTO-0035	Leak Stop Additive - No warranty on this service or refrigerant. Leak Stop is considered as an alternative approach to seal any microscopic leaks but success is not guaranteed. This may be used in a situation where refrigeration repairs are not possible	\$275.77
REFC-PRESS-0030	Replace/Install Pressure Switch - 1-Year Parts & Labor Warranty. This service is for replacing and existing or installing a new pressure switch on a refrigeration system. Pressure switches are crucial in that they protect the compressor from scenarios of	\$235.96
REFC-REP1-0030	Minor Refrigerant Leak Repair - Limited Lifetime Craftsmanship Warranty on Braze or Flared Joints. May not include refrigeration services such as but not limited to pumpdown recovery vacuum and recharging. Customer is advised to have regular preventat	\$179.72
REFC-REP2-0060	Major Refrigerant Leak Repair - Limited Lifetime Craftsmanship Warranty on Braze or Flared Joints. May not include refrigeration services such as but not limited to pumpdown recovery vacuum and recharging. Customer is advised to have regular preventat	\$357.02
REFC-TXVB-0030	Replace TXV (Mechanical Fitting Type) - 1-Year Parts & Labor Warranty. May not include refrigeration services such as but not limited to pumpdown recovery vacuum and recharging. Customer is advised to have regular preventative maintenance performed to	\$179.72
REFC-TXVS-0060	Replace TXV (Sweat Fitting Type) - 1-Year Parts & Labor Warranty. May not include refrigeration services such as but not limited to pumpdown recovery vacuum and recharging. Customer is advised to have regular preventative maintenance performed to help	\$357.02
REFC-TXVW-0060	Replace Warranty TXV (Sweat or Mechanical Fitting Type) - 1-Year Parts & Labor Warranty. May not include refrigeration services such as but not limited to pumpdown recovery vacuum and recharging. Customer is advised system operating and refrigerant cha	\$412.02
REFR-PUMP-0090	Pumpdown and Evacuation - This procedure is used to contain refrigerant in outdoor unit without the need for recovery. While this procedure is less expensive not all systems are capable of allowing this procedure. Customer is advised there is a chance of	\$771.33
REFR-R22-0120	Recovery Evacuation Recharge (HCFC R22) - Includes new drier and recharging with new HCFC R22 refrigerant. Customer is advised HCFC R22 refrigerant has been phased-out since January 2020 and is no longer in production. Deep evacuation will be performed	\$1,563.65
REFR-R410-0120	Recovery Evacuation Recharge (HFC R410A) - Includes new drier and recharging with new HFC R410A refrigerant. Deep evacuation will be performed to 700 microns or lower to remove air and moisture from opened sections of refrigeration system.	\$983.27



Name	Sales Desc	Price
REFR-R900-0120	Recovery Evacuation Recharge (Other Refrigerant) - Includes new drier and recharging with new refrigerant of any type that is not R22 or R410A. Deep evacuation will be performed to 700 microns or lower to remove air and moisture from opened sections of	\$983.27
REFR-RECO-0015	Recover Refrigerant of Any Type - This service includes recovering refrigerant and returning used refrigerant to be reclaimed at an appropriate facility per EPA Section 608 Guidelines.	\$89.65
REL-0001-0015	Attempt to Clean Contactor - No warranty on service. This is an alternative service offered in lieu of replacing the contactor when an insect is blocking the contacts.	\$43.00
REL-0340-0030	Replace DPDT Relay (90-340) - 1-Year Parts & Labor Warranty. This is a critical part. Customer is advised underlying issues may exist and may not be fully known until this part is replaced and additional repairs may be necessary. Customer is advised to ha	\$225.90
REL-0380-0030	Replace SPNO/SPNC Relay (90-380) - 1-Year Parts & Labor Warranty. This is a critical part. Customer is advised underlying issues may exist and may not be fully known until this part is replaced and additional repairs may be necessary. Customer is advised	\$208.04
REL-1P40-0030	Replace Single-Pole Contactor (up to 40A rating) - 1-Year Parts & Labor Warranty. This is a critical part. Customer is advised underlying issues may exist and may not be fully known until this part is replaced and additional repairs may be necessary. No w	\$216.79
REL-293Q-0030	Replace SPDT Relay (90-293Q) - 1-Year Parts & Labor Warranty. This is a critical part. Customer is advised underlying issues may exist and may not be fully known until this part is replaced and additional repairs may be necessary. Customer is advised to h	\$213.01
REL-2P40-0030	Replace Two-Pole Contactor (up to 40A rating) - 1-Year Parts & Labor Warranty. This is a critical part. Customer is advised underlying issues may exist and may not be fully known until this part is replaced and additional repairs may be necessary. No warr	\$221.22
S/A Commercial Addons	Commercial Service Agreement Addons - This line item is for specifying number of filters belts or other services included with a Commercial Service Agreement.	\$143.85
THERM-0001-0060	Relocate and Rewire Thermostat - 1-Year Parts & Labor Warranty. Service for relocating existing thermostat from one place to another. Customer is advised Automatic Climate may not provide cosmetic services such as patching drywall or painting unless spe	\$255.62
THERM-0003-0015	Replace/Install Thermostat Wire - 1-Year Parts & Labor Warranty. Service for replacing a section existing or run new thermostat from one place to another. Customer is advised Automatic Climate may not provide cosmetic services such as patching drywall or	\$132.17
THERM-00T6-0035	Install Honeywell T6 Non-Programmable Thermostat 2H/1C - 1-Year Parts & Labor Warranty 5-Year Honeywell Parts Warranty.	\$99.42



























































